






Make sure that the service penetration and the gap are free from dust, dirt and grease.




Measure the circumference of the service penetration and cut the Multiwrap to size with a knife. Remember to keep an extra length of at least 10 mm to create an overlap.



Seal the remaining recess with Multimastic SP or with the Multimastic C System or Multimortar System.



The Multiwrap may protrude a maximum of 5 mm.



Wrap the required number of layers of Multiwrap around the service penetration.



Fill in the conformity statement and paste it next to the fireproof seal.





















